



TECHNICAL

BULLETIN

TECHNICAL BULLETIN: 13-21

DATE: July 19, 2013

SUBJECT: Release of Triton Connect v5.8 SP3 Software

AVAILABILITY: All Authorized Triton Distributors and Third Party Service Providers

This bulletin addresses:		Recommended Implementation is:	
	Documentation Changes		Now for all affected units
	Hardware Service Issues		All affected units during next service visit
X	Software Announcements		Optional
	Technical Tips	X	No implementation required

DESCRIPTION:

Triton announces the release of Triton Connect v5.8 SP3 Software. Triton Connect is a PC (Personal Computer) based software that enables you to remotely manage one or more Triton Systems ATMs. Triton Connect is a proven ATM monitoring solution which is currently being used to manage literally thousands of Triton Systems ATMs throughout the United States and abroad.

The latest release of Triton Connect has a number of new and modified features. The following is a list of features that are either new or have been modified in the latest release of Triton Connect 5.8 SP3.

- Adds the ability to update the IP address that it stores from the ATM contacting Triton Connect
- Addresses the issue of an error message given by the Call Monitor if no COM Port exists
- Addresses the issue of an error 9 message experienced with a high volume of incoming connection requests.
- Read the Release Notes on the Triton web site for further clarification.

If you have any questions, please contact Technical Support or our Parts Department at 1-228-575-3100 from outside North America or toll free in the U.S./ Canada 1-800-259-6672 or visit www.Triton.com for additional information.