

866-787-4866 21405 B Street, Long Beach, MS 39560



## **TECHNICAL BULLETIN**

SUBJECT:
TLS UPDATES FOR TRITON CONNECT

TECHNICAL TIP: 17-11
DATE: AUGUST 28, 2017

## TRITON TECHNICAL TIP – UPDATING CERTIFICATES WITH TRITON CONNECT

If Triton Connect certificates are updated and/or changed, TLS updates may be required for each ATM communicating with Triton Connect.

TLS updates must be loaded onto ATM before certificates are updated and/or changed for Triton Connect. Failure to do so may cause a failure in Triton Connect communications and require a site visit to the ATM to correct.

Please refer to Technical Bulletin 16-10 and 16-12 for more information. Release notes are available at www.trito-natm.com. Software released in these technical bulletins include all necessary certificates for the following units:

RL1600	RL2000	Traverse (RL3300)
RL5000	FT5000	RT2000
ARGO 7	ARGO 12	ARGO 15

Software must be version 2.4.0 or greater. If the tsocketocx file is version 3.0.0.2 or higher, no further action is required. If tsocketocx is prior to 3.0.0.2, a software update must be performed.



**xu20tsck3.0.0.4.tlf** for Xscale update **t-us-tsck-3.0.0.2d.tr6** for X2 CE6 update

xu30tsck3.0.0.2d.tfv for X2 CE5 update t-us-tsck-3.0.0.2d.tr7 for X3 update

If you have questions regarding this Technical Bulletin, please contact Technical Support at 1-228-575-3100, option 4 or toll free in the U.S. / Canada 1-866-259-6672, option 4. Visit www.tritonatm.com for additional information. For all ATM parts, repair, and training needs, visit www.atmgurus.com.

