

**SUBJECT:**  
**TRITON CONNECT 6.1 SERVICE PACK 2**

**TECHNICAL BULLETIN: 18-12**  
**DATE: SEPTEMBER 06, 2018**

**Confidential - Available to all authorized Triton distributors and third party service providers**

## OPTIONAL SOFTWARE UPGRADE – RELEASE OF TRITON CONNECT 6.1 SP2

Triton announces the release of Triton Connect 6.1 SP2. Service Pack 2 includes an updated Terminal Manager graphic and a new downtime report. The downtime report details how long individual terminals are out of service per error code.



### Triton Connect Terminal Down Time Per Error Report

4/16/2018	Down Time From 3/23/2017	To 4/25/2017
Terminal	Error	Down Time (hh:mm:ss)
RL332	101 - Error in waiting for pick	0:02:18

Also included with this release is restored functionality to modify E-flags, and IP address indication for clients that attempt to connect on the port configured for SSL. Other updates and fixes include adjustments to system performance and improved functionality for Terminal ID searches. For a full description of changes and updates, see the release notes at [www.tritonatm.com](http://www.tritonatm.com).

**\*\*Note\*\***

A new comloc will be required if upgrading from Triton Connect 5.x or earlier.

If you have questions regarding this Technical Bulletin, please contact Technical Support at 1-228-575-3100, option 4 or toll free in the U.S. / Canada 1-866-787-4866, option 4. Visit [www.tritonatm.com](http://www.tritonatm.com) for additional information. For all ATM parts, repair, and training needs, visit [www.atmgurus.com](http://www.atmgurus.com).