

TECHNICAL

BULLETIN

TECHNICAL BULLETIN: 12-07

DATE: July 27, 2012

SUBJECT: Release of updated Printer Assembly for the Traverse ATM

AVAILABILITY: All Authorized Triton Distributors and Third Party Service Providers

This bulletin addresses:	Recommended Implementation is:
Documentation Changes	Now for all affected units
X Hardware Service Issues	All affected units during next service visit
Software Announcements	Optional
Technical Tips	X No implementation required

DESCRIPTION:

Triton announces the release of an updated printer assembly for the Traverse model ATM.

The new printer assembly incorporates a new printer controller board. The complete printer assembly is backward compatible into the earlier models originally delivered with the earlier printer assembly.

The controller board, printer, or other individual components are not backward compatible. Availability of the older printer assembly and individual parts will be limited.

Model numbers for the older and newer assemblies are:

- SRU-S2 previous
- LRPU V current

Model numbers can be found on the white sticker on the left side of the printer assembly.

Printer firmware identification is also available on the Configuration Summary or Diagnostics>Printer>Device Status report.

Model Firmware version

- SRU-S2 Hantel LPU06
- LRPU V Hantel TPU06





New Traverse units beginning with the following serial numbers will have the new printer assembly.

RL331B LRL331B12073xxxx

RL3310 LRL331012114xxxx

RL3314 LRL331412114xxxx

RL331D LRL331D12122xxxx HCDU (two high dispenser) will only have the new printer.

Remember: DIP switch settings for Triton ATMs using both printer styles are 1 & 7 ON, all others OFF. If DIP switch settings are made, the reset button must be pushed to activate the changes.

If you have any questions, please contact Technical Support or our Parts Department at 1-228-575-3100 from outside North America or toll free in the U.S./ Canada 1-800-259-6672.