



# TECHNICAL

# BULLETIN



## TECHNICAL BULLETIN: 14-11

**DATE:** April 14, 2014

**SUBJECT:** Triton Not Affected by OpenSSL Heartbleed bug

**AVAILABILITY:** All Authorized Triton Distributors and Third Party Service Providers

This bulletin addresses:	
<input type="checkbox"/>	Hardware Service Issues
<input type="checkbox"/>	New Kit/Parts Available
<input type="checkbox"/>	Software Announcements
<input checked="" type="checkbox"/>	Technical Tips

Recommended Implementation is:	
<input type="checkbox"/>	Now for all affected units
<input type="checkbox"/>	All affected units during next service visit
<input type="checkbox"/>	Optional
<input checked="" type="checkbox"/>	No implementation required

## DESCRIPTION:

Recently the OpenSSL project announced a security vulnerability in the OpenSSL libraries nicknamed %Heartbleed+. The Heartbleed bug is a major vulnerability in OpenSSL that compromises the integrity of data secured through SSL. This vulnerability is limited to applications that use the OpenSSL libraries.

None of Triton Systems\$ products, including ATMs and Triton Connect, use the OpenSSL library, so these products are not affected.

If you have questions regarding this Technical Bulletin, please contact Technical Support at 1-228-575-3100 or toll free in the U.S. / Canada 1-800-259-6672.

Visit [www.Triton.com](http://www.Triton.com) for additional information.

For all ATM Parts, Repair, and Training needs, visit [www.atmgurus.com](http://www.atmgurus.com).