







SUBJECT:

US 7.3/7.4 EMV PLUG-IN FOR LEGACY ATMS

TECHNICAL BULLETIN: 16-16

DATE: NOVEMBER 17, 2016

Available to all authorized Triton distributors and third party service providers.

SOFTWARE ANNOUNCEMENT UPDATE REQUIRED FOR 8100 / 9100 / 9600 / 9700 ATMS

Triton announces the release of a software update for the US market, distributed as a plug-in, for 8100/9100/9600/9700 ATMs. This release resolves a field issue regarding an ATM reboot when certain cards were used, and adds support for EMV AIDS for 7.4. Refer to software release notes for more information.

Model	New EMV Application Plug-in	Terminal Software Required
9100/8100 7.3	emva0809.B91	кс990088.15 (color) кр990088.15 (monochrome)
9100/8100 7.4	EMVA0904.B91	кс990088.17 (color) кр990088.17 (monochrome)
9600 7.3	emva0809.b96	XD890080.11 (color) XD880080.11 (monochrome)
9600 PCI 7.3	emva0809.b96	XD920080.02 (color) XD910080.02 (monochrome)
9700 7.3	EMVA0809.B97	zD990080.08 (color)

Note

The EMV kernel plug-in has not changed. As new plug-ins are developed and released, these may be installed independently.

This update replaces the previous plug-in files: EMVA0808.B91, EMVA0902.B91, EMVA0807.B96 and EMVA0807.B97. Please see release notes for hardware compatibility. Release notes and software load files can be found at www.tritonatm.com.

If you have questions regarding this Technical Bulletin, please contact Technical Support at 1-228-575-3100, option 4 or toll free in the U.S. / Canada 1-800-259-6672, option 4. Visit www.tritonatm.com for additional information. For all ATM parts, repair, and training needs, visit www.atmgurus.com.

ECO: 1031287