





TECHNICAL BULLETIN

CONFIDENTIAL

SUBJECT: TECHNICAL BULLETIN: 17-01

RELEASE OF US 4.0.0 SERVICE PACK 2 FOR X2 CE6 AND X3 CE7 DATE: JANUARY 05, 2017

Available to all authorized Triton distributors and third party service providers.

MANDATORY SOFTWARE UPGRADE: RELEASE OF US 4.0.0 SP2 FOR X2 CE6 AND X3 CE7

Triton announces the release of X2 CE6 4.0.0 SP 2 and X3 CE7 4.0.0 SP2, which includes EMV updates for the US. This software supports the Sankyo ICM330 dip-style card reader, and adds support for the Sankyo ICT3K7 motorized card reader. Software upgrade can be found at https://www.tritonatm.com. Please review release notes for more information. The following load files are included with this release:

Model	Display	File
RL53	10.4"	t-us-xcae-4.0.0.18sp2.tr6
FT53	10.4"	t-us-xcae-4.0.0.18sp2.tr6
RL23	8"	t-us-xcae-4.0.0.18sp2.tr6
ARGO 7	7"	t-us-wtcs-4.0.0.18sp2.tr6
ARGO 12	12.1"	t-us-scsf-4.0.0.18sp2.tr6
ARGO 15	15"	t-us-bcsf-4.0.0.18sp2.tr7
Traverse	8"	t-us-wcse-4.0.0.18sp2.tr6

Note

Must be loaded on top of any US 4.0.0.18 or earlier software version. The program build after upgrading will be 4.0.0.18f.

To verify if software has been loaded onto ATM, check program build via Management Functions main menu.

Benefits of Updating toX2 CE6 4.0.0 SP2 include:

- EMV updates for Visa Plus, Discover, MasterCard, JCB, and DNA
- EMV PIN change update
- EMV support for audio transactions
- Rear service panel denomination change and rear service panel cassette close

X2 CE6 4.0.0 SP 2 also includes changes previously released in SP1. See software release notes on www.tritonatm. com for more information.

If you have questions regarding this Technical Bulletin, please contact Technical Support at 1-228-575-3100, option 4 or toll free in the U.S. / Canada 1-800-259-6672, option 4. Visit www.tritonatm.com for additional information. For all ATM parts, repair, and training needs, visit www.atmgurus.com.

ECO: 1031081