

866-787-4866 21405 B Street, Long Beach, MS 39560



## TECHNICAL BULLETIN

SUBJECT: TECHNICAL BULLETIN: 17-09

LED SIGN BACKLIGHT DATE: AUGUST 17, 2017


Confidential - Available to all authorized Triton distributors and third party service providers

## **OPTIONAL UPGRADE: LED SIGN BACKLIGHT**

Triton announces a new, improved lighting solution to replace the LED sign lighting used in current products. Beginning immediately, all new and refurbished units will ship with the new, trapezoidal LED sign light. Kits will be available for field replacements via <a href="https://www.atmgurus.com">www.atmgurus.com</a> or by calling Customer Service at 1 (228) 575-3100, option 3.

Model	Part Number	Description	
ARGO RL2	06100-00144	LED Board Replacement Kit for Integrated Sign or Mid Topper with Contoured Bracket	
ARGO 9700 RL2 RL5	06100-00143	LED Board Replacement Kit for Fluorescent or LED High Topper	, and the second
RL5	06200-00180	LED Board Replacement Kit for Direct Lighting LED High Topper	
8100 9100 RL2 RL5	06200-08213	LED Board Replacement for Mid Topper with Flat Back Bracket	







06100-00143 shown above



06200-00180 shown above

06200-08213 shown above

If you have questions regarding this Technical Bulletin, please contact Technical Support at 1-228-575-3100, option 4 or toll free in the U.S. / Canada 1-800-259-6672, option 4. Visit www.tritonatm.com for additional information. For all ATM parts, repair, and training needs, visit www.atmgurus.com.



ALL REPAIRS MUST BE ON A SINGLE RMA, INCLUDING ALL 6 ITEMS FOR REPAIR, AND MUST BE SHIPPED BACK TO SAME ADDRESS

**REPAIR NOW!**