

**SUBJECT:**  
**RELEASE OF US VERSION 7.4D SOFTWARE**

**TECHNICAL BULLETIN: 18-06**  
**DATE: MAY 01, 2018**

**Confidential - Available to all authorized Triton distributors and third party service providers**

**SOFTWARE ANNOUNCEMENT –**  
**REQUIRED UPDATE FOR ANY US 81XX, 91XX, 96XX, OR 97XX ATM.**

Triton announces the release of a software update for the US Market for all 81XX, 91XX, 96XX, and 97XX ATMs. This release incorporates numerous incremental changes and improvements, such as improved EMV functionality, and improved support for the advanced security module. Numerous updates from previous plug-ins are also included in this release.

Supported hardware and software file names for each model are listed in the tables below. Software can be found at [www.tritonatm.com](http://www.tritonatm.com). Please review software release notes for details and a full list of changes included.

Model	Full Load Software Version	Update Software Version
81XX 91XX	KC990088.26 (color display) KD990088.26 (monochrome display)  To enable Advanced Security Module support, the following plug-in must be installed: AVSM0200.B91  To enable EMV support, the following plug-ins must also be installed: EMVK0100.B91 EMVA1102.B91	KCT-9988.26 (color display) KAT-9988.26 (monochrome display)  To enable Advanced Security Module support, the following plug-in must be installed: AVSM0200.B91  To enable EMV support, the following plug-ins must also be installed: EMVK0100.B91 EMVA1102.B91
96XX	XD890080.15 (color display) XD880080.15 (monochrome display)  To enable Advanced Security Module support, the following plug-in must be installed: AVSM0200.B96  To enable EMV support, the following plug-ins must also be installed: EMVK0100.B96 EMVA1102.B96	XAT-8980.15 (color display) XAT-8880.15 (monochrome display)  To enable Advanced Security Module support, the following plug-in must be installed: AVSM0200.B96  To enable EMV support, the following plug-ins must also be installed: EMVK0100.B96 EMVA1102.B96

Model	Full Load Software Version	Update Software Version
96XX PCI	<p>XD920080.06 (color display) XD910080.06 (monochrome display)</p> <p>To enable Advanced Security Module support, the following plug-in must be installed: AVSM0200.B96</p> <p>To enable EMV support, the following plug-ins must also be installed: EMVK0100.B96 EMVA1102.B96</p>	<p>XAT-9280-06 (color display) XAT-9180.06 (monochrome display)</p> <p>To enable Advanced Security Module support, the following plug-in must be installed: AVSM0200.B96</p> <p>To enable EMV support, the following plug-ins must also be installed: EMVK0100.B96 EMVA1102.B96</p>
97XX	<p>ZD990080.12</p> <p>To enable Advanced Security Module support, the following plug-in must be installed: AVSM0200.B97</p> <p>To enable EMV support, the following plug-ins must also be installed: EMVK0100.B97 EMVA1102.B97</p>	<p>ZAT-9980.12</p> <p>To enable Advanced Security Module support, the following plug-in must be installed: AVSM0200.B97</p> <p>To enable EMV support, the following plug-ins must also be installed: EMVK0100.B97 EMVA1102.B97</p>

**If you have questions regarding this Technical Bulletin, please contact Technical Support at 1-228-575-3100, option 4 or toll free in the U.S. / Canada 1-866-787-4866, option 4. Visit [www.tritonatm.com](http://www.tritonatm.com) for additional information. For all ATM parts, repair, and training needs, visit [www.atmgurus.com](http://www.atmgurus.com).**