

866-787-4866 21405 B Street, Long Beach, MS 39560



TECHNICAL BULLETIN

SUBJECT:

4.1 SOFTWARE FOR ARGO 15 AND ARGO FT

TECHNICAL BULLETIN: 18-13

DATE: SEPTEMBER 25, 2018

Confidential - Available to all authorized Triton distributors and third party service providers

OPTIONAL UPGRADE – US, CANADIAN, AND AUSTRALIAN 4.1 SOFTWARE FOR ARGO 15 AND ARGO FT X3

Triton announces the release of X3 4.1 software for ARGO 15 and ARGO FT for the US, Canadian, and Australian markets. This release includes multiple new features, such as a new user interface, DCC, updated default messages, cardless transactions, and more detailed information for terminal error messages on the out of service screen. This update also corrects an issue where user permissions were not applied to the rear service panel for certain functions on the ARGO FT.

Software can be found at www.tritonatm.com. The following load files are included with this release:

Model	Load File	Country
ARGO FT /ARGO 15	t-fs-bcsf-4.1.0.40.tr7	US, Canada, Australia

After loading software, the program build will be 4.1.0.40 and the screen file will be BCSF0017.

After software installation on ARGO FT ATMs, navigate to *Management Functions > Terminal Configuration > Optional Screens* and enable ARGO FT Hardware.

See applicable release notes for a detailed description of changes and features. Release notes can be accessed via Triton's new software download wizard at www.tritonatm.com.



If you have questions regarding this Technical Bulletin, please contact Technical Support at 1-228-575-3100, option 4 or toll free in the U.S. / Canada 1-866-787-4866, option 4. Visit www.tritonatm.com for additional information. For all ATM parts, repair, and training needs, visit www.atmgurus.com.

ECO: 1032128