TECHNICAL BULLETIN
CONFIDENTIAL

SUBJECT: Releasing Glory firmware 2011-02.07 for MiniMech Dispensers.

AVAILABILITY: All Authorized Triton Distributors and Third Party Service Providers

This bulletin addresses:		Recommended Implementation is:	
	Hardware Service Issues		Now for all affected units
	New Kit/Parts Available		All affected units during next service visit
X	**Software Announcements**		Optional
	Technical Tips	X	**No implementation required**

DESCRIPTION:

Triton announces the release of firmware 2011-02.07 for Glory MiniMech Dispensers. This firmware has completed Triton testing and improves rejects for Canadian polymer notes.

All MiniMech dispensers shipped to Triton from Glory will contain the new Firmware v2011-02.07. Triton Repair, Refurb, and Production Units will install the new firmware as needed.

This Firmware is not available for download on the website.

If you have questions regarding this Technical Bulletin, please contact Technical Support at 1-228-575-3100 or toll free in the U.S. / Canada 1-800-259-6672. Visit www.tritonatm.com for additional information.

For all ATM Parts, Repair, and Training needs, visit www.atmgurus.com.

ECO# 1030923