TECHNICAL BULLETIN
CONFIDENTIAL

SUBJECT: Release of EMV Anti-Skim Card Reader Upgrade Kit for ARGO 15, RL53XX, and FT53XX. **(Revised to include ARGO 7)**

AVAILABILITY: All Authorized Triton Distributors and Third Party Service Providers

This bulletin addresses:		Recommended Implementation is:	
	Hardware Service Issues		Now for all affected units
X	**New Kit/Parts Available**		All affected units during next service visit
X	**Software Announcements**	X	**Optional**
	Technical Tips		No implementation required

DESCRIPTION:

Triton announces the release of EMV Anti-Skim Card Reader Upgrade Kits for the RL53XX, FT53XX, ARGO 7, and ARGO 15. This product is available as an option when purchasing a new ATM, or as an upgrade for existing machines. Anti-Skim Card Reader Upgrade kits are available for purchase by calling 1-800-259-6672, or visiting https://www.atmgurus.com/ and searching the applicable part number:

This product requires a software upgrade, which can be found at https://www.tritonatm.com/. Please review release notes for more information.

t-fs-bcsf-4.0.0.33.tr7 **X3** for ARGO 15, United States and Canada

t-fs-xcse-4.0.0.36.tr6 **X2 CE6** for RL/FT 5000, United States and Australia

t-fs-xcae-4.0.0.36.tr6 **X2 CE6** for RL/FT 5000, Canada

t-fs-wtcs-4.0.0.35.tr6 **X2 CE6** for ARGO 7, United States, Canada, and Australia

** Note **
Only X2 CE6 boards can be loaded with this software.

Please see page 2 for additional details.

If you have questions regarding this Technical Bulletin, please contact Technical Support at 1-228-575-3100 or toll free in the U.S. / Canada 1-800-259-6672. Visit www.Triton.com for additional information.

**For all ATM parts, repair, and training needs, visit www.atmgurus.com.**

ECO# 1031177,1031173,
1031018,1031095
1031210

TECHNICAL BULLETIN
CONFIDENTIAL

06200-00355

Upgrade from I-65 or Track 1-2 card
reader for RL53, ARGO 7, and ARGO 15

06200-00358

Upgrade from ICM330 EMV card
reader for RL53, ARGO 7, and ARGO 15

06200-00402

Upgrade for FT53 with Track 1-2, I-65, or
ICM330 card reader.

**If you have questions regarding this Technical Bulletin, please contact Technical
Support at 1-228-575-3100 or toll free in the U.S. / Canada 1-800-259-6672.
Visit www.Triton.com for additional information.**

For all ATM parts, repair, and training needs, visit www.atmgurus.com.