TECHNICAL BULLETIN

CONFIDENTIAL

SUBJECT: TLS UPDATE FOR SWITCH COMMERCE	**TECHNICAL BULLETIN:** 16-10 **DATE: OCTOBER 03, 2016**

Available to all authorized Triton distributors and third party service providers.

SOFTWARE UPDATE REQUIRED.

TRITON RELEASES NEW TLS UPDATE FOR ALL CUSTOMERS WHO PROCESS WITH SWITCH COMMERCE.

This document describes an upgrade load file which allows Xscale, X2, or X3 ATMs to accept SSL host certificates for Switch Commerce. The ATM s**oftware must be updated** so that the newer certificates can be accepted.

Beginning October 05, 2016, all Triton parts orders, repair orders, new ATMs and refurbished ATMs will ship with this update pre-loaded. Switch Commerce has released their update schedule to their customers.

This release includes all necessary certificates for the following units:

RL1600	RL2000	Traverse (RL3300)
RL5000	FT5000	RT2000
ARGO 7	ARGO 12	ARGO 15

No specific hardware is required for the update. Software must be version 2.4.0 or greater. To access update, click here, or visit www.tritonatm.com.

> **xu20tsck3.0.0.3.tlf**   for Xscale update
> **xu30tsck3.0.0.2d.tfv**   for X2 CE5 update
> **t-us-tsck-3.0.0.2d.tr6** for X2 CE6 update
> **t-us-tsck-3.0.0.2d.tr7** for X3 update

If you have questions regarding this Technical Bulletin, please contact Technical Support at 1-228-575-3100 or toll free in the U.S. / Canada 1-800-259-6672. Visit www.tritonatm.com for additional information. For all ATM parts, repair, and training needs, visit www.atmgurus.com.