Triton®
Partnership Measured in Decades...

866-787-4866
21405 B Street, Long Beach, MS 39560

atmgurus®
just ask us...

TECHNICAL BULLETIN

SUBJECT:	TECHNICAL BULLETIN: 22-02
ARGO 4.2 MMR050 SOFTWARE RELEASE NOTES	DATE: FEBRUARY 10, 2022

Confidential - Available to all authorized Triton distributors and third party service providers

OPTIONAL UPDATE - RELEASE OF US AND CANADIAN
VERSION 4.2 MMR050 SOFTWARE UPDATE FOR ARGO 7, 12, AND 15 X3 ATMS

Triton announces the release of version 4.2 MMR050 single cassette software support for ARGO 7, 12, and 15 X3 ATMs. The dispenser information shows in the configuration summary. This release provides MMR050 Error Codes and how they are mapped to the ATM error codes. Also, the error codes are recorded in the journal with error details similar to the other dispensers.

The following load files are included in this release. The program build after loading will be 4.2.3.6. The screen file will be WTCS0057 for (ARGO 7), SCSF0043 for (ARGO 12), and BCSF0027 for (ARGO 15). Software can be found at www.triton.com.

Model	Load File
ARGO 7	t-fs-wtcs-4.2.3.6.tr7
ARGO 12	t-fs-scsf-4.2.3.6.tr7
ARGO15	t-fs-bcsf-4.2.3.6.tr7

For detailed information on the above options and other improvements, please read the full release notes at www.triton.com/services & support/software download. Click the Software Download icon.

If you have questions regarding this Technical Bulletin, please contact Technical Support at 1-228-575-3100, option 3 or toll free in the U.S. / Canada 1-866-787-4866, option 3. Visit www.triton.com for additional information. For all ATM parts, repair, and training needs, visit www.atmgurus.com.

ECO: 1033030