

# TECHNICAL

# BULLETIN

**TECHNICAL BULLETIN: 12-09**

**DATE:** September 26, 2012


**SUBJECT:** Cassette Height Adjustment on HCDU/SCDU for Canada

**AVAILABILITY:** All Authorized Triton Distributors and Third Party Service Providers

This bulletin addresses:	Recommended Implementation is:
Documentation Changes	<b>X Now for all affected units</b>
Hardware Service Issues	All affected units during next service visit
Software Announcements	Optional
<b>X Technical Tips</b>	No implementation required

## DESCRIPTION:

HCDU/SCDU dispensers (as may be found in the Triton Traverse) require a height adjustment of the cassette(s) for Canadian currency. If an HCDU or SCDU cassette is found still set to US configuration, the adjustment can be made by simply removing the height rails from the cassette lid, rotating them, and reattaching with the same screws.



Traverse units shipped to Canada should be configured for Canadian currency prior to shipment from Triton.

**If you have any questions, please contact Technical Support or our Parts Department at 1-228-575-3100 from outside North America or toll free in the U.S./ Canada 1-800-259-6672.**