



TECHNICAL

BULLETIN

TECHNICAL BULLETIN: 13-09

DATE: April 19, 2013

SUBJECT: Release TDM Firmware Loader for Canada v14.01B

AVAILABILITY: All Authorized Canadian Triton Distributors and Third Party Service Providers

This bulletin addresses:		Recommended Implementation is:	
	Documentation Changes	X	Now for all affected units
	Hardware Service Issues		All affected units during next service visit
X	Software Announcements		Optional
	Technical Tips		No implementation required

DESCRIPTION:

Triton announces the release of TDM Firmware Loader for Canada v14.01B. This latest version adds the ability to upgrade TDM's with stepper motors to dispense Canadian polymer currency more reliably. Support for upgrading the firmware for TDM50s and TDM1XX/2XX with DC motors is also included.

The TDM Firmware Loader for Canada v14.01B software application and instructions are available for download from the Triton partner site.

Note: TDM Firmware Loader for Canada v14.01B cannot upgrade TDMs that will be used in the 9700 ATM. A special firmware loader is being created for use when upgrading TDMs for this model ATM.

As with the previous version of TDM Firmware Loader for Canada, the application is comloc controlled and requires a special download cable for firmware upgrades. Kits that include both the comloc and download cable may be order from Triton using part number **06300-00004**.

Customers that purchased kits to use with the previous version of TDM Firmware Loader for Canada can continue to use their kits with this latest software.

Additional TDM firmware updates can be ordered from Triton as needed.

If you have any questions, please contact Technical Support or our Parts Department at 1-228-575-3100 from outside North America or toll free in the U.S./ Canada 1-800-259-6672.