



TECHNICAL

BULLETIN

TECHNICAL BULLETIN: 13-15

DATE: June 14, 2013

SUBJECT: Release of MiniMech Firmware 2011.02.06

AVAILABILITY: All Authorized Triton Distributors and Third Party Service Providers

This bulletin addresses:		Recommended Implementation is:	
	Documentation Changes		Now for all affected units
	Hardware Service Issues		All affected units during next service visit
X	Software Announcements		Optional
	Technical Tips	X	No implementation required

DESCRIPTION:

Triton announces the release of MiniMech firmware 2011.02.06. This firmware update is identical to the preliminary released MiniMech firmware 2011.02.FD which addressed issues with dispensing Canadian polymer currency. MiniMech dispensers operating in Canada and dispensing Canadian polymer notes require either 2011.02.FD or 2011.02.06 firmware.

There is no need to update from 2011.02.FD to 2011.02.06 firmware. Customers in countries other than Canada do NOT need to update their current dispensers with 2011.02.06 firmware.

As of March 1, 2013, all new and refurbished MiniMech dispensers purchased from Triton are loaded with this new firmware.

If you have any questions, please contact Technical Support or our Parts Department at 1-228-575-3100 from outside North America or toll free in the U.S./ Canada 1-800-259-6672.