



TECHNICAL

BULLETIN

TECHNICAL BULLETIN: 13-20

DATE: July 1, 2013

SUBJECT: Release of US Software Version 3.2 for XScale

AVAILABILITY: All Authorized Triton Distributors and Third Party Service Providers

This bulletin addresses:		Recommended Implementation is:	
	Documentation Changes	X	Now for all affected units
	Hardware Service Issues		All affected units during next service visit
X	Software Announcements		Optional
	Technical Tips		No implementation required

DESCRIPTION:

Triton announces the release of **Software Version 3.2 for the US** for the following Triton ATMs with the XScale controller: RL5XXX, FT5XXX and RT2XXX 10.4 display for XScale. Read this bulletin and the release notes carefully before deciding to upgrade your software. Release notes (*XS 3.2.0 US Software Release Notes.pdf*) may be found on the Triton partner website (www.TritonATM.com).

New features include:

• EMV Capability

An EMV Level 2 compliant kernel that is capable of processing ICC cards is included in this software. In order to enable EMV on the ATM,

- 1) An EMV card reader (Sankyo ICM330 or Sankyo ICT3K5/7) must be installed, and
- 2) To activate EMV, the customer must enter a code on the ATM. This code will be provided by Technical Support or via the Triton website (www.tritonatm.com). Call your salesperson for further details.

(Note: Before attempting to activate, check with the host processor to ensure host provides EMV support.)

• Vault Door Alarm Behavior

Door Open error clears automatically when the vault door is closed.



- **SSL Certificates**

Certain SSL certificates are included in this release and will not need to be installed separately.

Please read the Software Release Notes for more details and additional functionalities not listed above.

If you have any questions, please contact Technical Support or our Parts Department at 1-228-575-3100 from outside North America or toll free in the U.S./ Canada 1-800-259-6672 or visit www.Triton.com for additional information.