

TECHNICAL BULLETIN: 13-25

DATE: August 28, 2013

SUBJECT: [LED Replacement Backlight Bulbs for High Bright RT2/FT5 Display](#)

AVAILABILITY: All Authorized Triton Distributors and Third Party Service Providers

This bulletin addresses:	
	Hardware Service Issues
X	New Kit/Parts Available
	Software Announcements
	Technical Tips


Recommended Implementation is:	
	Now for all affected units
	All affected units during next service visit
X	Optional
	No implementation required

DESCRIPTION:

Triton announces the release of the CCFL to LED Backlight Bulb Replacement Kit for the RT2xxx and FT5xxx units. A complete kit including two High Bright LED Strip Backlights and one LED Driver Board is available on ATMGurus.com as **part # [06200-00185](#)**.

The LED backlight bulbs provide more stability with improved technology over the CCFL bulbs. The LED Backlight Bulb Replacement Kit has an average 50,000 hour life span and comes with a 12 month Triton warranty.

Once the display has been upgraded, individual parts can be ordered as LED strip part # [09100-00445](#) & driver board # [09100-00444](#). Inventory of the CCFL Backlight Bulbs (part # [01220-00024](#) & [01220-00012](#)) & CCFL Inverter Boards ([01290-00025](#)) are still available.



If you have questions regarding this Technical Bulletin, please contact Technical Support at 1-228-575-3100 or toll free in the U.S. / Canada 1-800-259-6672.

Visit www.Triton.com for additional information.

For all ATM Parts, Repair, and Training needs, visit www.atmgurus.com.