



TECHNICAL

BULLETIN



TECHNICAL BULLETIN: 14-05

DATE: February 20, 2014

SUBJECT: Release of the 2.8.0 SP2 for VersaSafe Units

AVAILABILITY: All Authorized Triton Distributors and Third Party Service Providers

This bulletin addresses:	
	Hardware Service Issues
	New Kit/Parts Available
X	Software Announcements
	Technical Tips

Recommended Implementation is:	
	Now for all affected units
	All affected units during next service visit
X	Optional
	No implementation required

DESCRIPTION:

Triton announces the release of the 2.8.0 SP2 for VersaSafe units. This software should be installed on 2.7.0 or 2.8.0. After loading the update, the program build in the configuration summary will indicate version 2.8.0.7.

This software release includes the following changes (please refer to the release notes for complete descriptions):

- System Clock Auto Correction
- Viewable Date/Time in Management Functions
- Auto Shift Close During Day Close Option
- Summary Report
- Dual BNF Feed Acceptance Behavior

This software load and release notes can be found on www.TritonATM.com.

If you have questions regarding this Technical Bulletin, please contact Technical Support at 1-228-575-3100 or toll free in the U.S. / Canada 1-800-259-6672.

Visit www.Triton.com for additional information.

For all ATM Parts, Repair, and Training needs, visit www.atmgurus.com.