

## TECHNICAL BULLETIN: 14-10

**DATE:** April 2, 2014

**SUBJECT:** Release of US EMV Software Version 7.3 and Sankyo ICM330 EMV Card Reader Kit for Triton 8100/9100 Model ATMs

**AVAILABILITY:** All Authorized Triton US Distributors and Third Party Service Providers

This bulletin addresses:	
<input type="checkbox"/>	Hardware Service Issues
<input checked="" type="checkbox"/>	<b>New Kit/Parts Available</b>
<input checked="" type="checkbox"/>	<b>Software Announcements</b>
<input type="checkbox"/>	Technical Tips

Recommended Implementation is:	
<input type="checkbox"/>	Now for all affected units
<input type="checkbox"/>	All affected units during next service visit
<input checked="" type="checkbox"/>	<b>Optional</b>
<input type="checkbox"/>	No implementation required

### DESCRIPTION:

Triton announces the release of US EMV Software Version 7.3 for the 8100 and 9100 ATMs. This software version supports the Sankyo ICM330 US EMV Upgrade Kit (part #06200-00352). Both this software version and the hardware kit are required for EMV level 2 functionality.

These software load files and their release notes can be found on [www.TritonATM.com](http://www.TritonATM.com). Please refer to the Software Release Notes for Hardware compatibility.



**06200-00352**  
**US EMV Card Reader Upgrade Kit**

**DESCRIPTION (Cont.):**

Software US revision 7.3 also supports the new External Ethernet Kits (part #[06200-00192](#) & #[06200-00135](#)) for 8100 and 9100.



**06200-00192**

**External Ethernet Replacement Kit**



**06200-00135**

**External Ethernet Upgrade Kit**

If you have questions regarding this Technical Bulletin, please contact Technical Support at 1-228-575-3100 or toll free in the U.S. / Canada 1-800-259-6672.

Visit [www.Triton.com](http://www.Triton.com) for additional information.

For all ATM Parts, Repair, and Training needs, visit [www.atmgurus.com](http://www.atmgurus.com).