



# TECHNICAL BULLETIN

## CONFIDENTIAL

**SUBJECT:**  
**9100 US 7.4 EMV PLUG-IN FILE EMVA0902**

**TECHNICAL BULLETIN: 16-09**  
**DATE: SEPTEMBER 21, 2016**

Available to all authorized Triton distributors and third party service providers.

### *SOFTWARE ANNOUNCEMENT -*

### *UPDATE REQUIRED FOR ANY 9100 ATM WITH AN ADVANCED SECURITY MODULE (ASM) WITH SDD OR MINI-MECH DISPENSERS*

Triton announces the release of a software update for the US market, distributed as a plug-in, for 9100 ATMs equipped with an ASM and Mini-Mech or SDD dispenser. This release resolves an issue with incorrect EMV tags being sent in EMV message requests. The plug-in replaces the current EMVA0901.B91 plug-in, and is necessary for any 9100 US ATM or main board that will be operating with an ASM with Mini-Mech or SDD dispenser. It is assumed that the required terminal software load file has already been uploaded on the terminal.

#### **\*\*Note\*\***

The EMV kernel plug-in has not changed. As new plug-ins are developed and released, these may be installed independently.

Software upgrade can be found at <https://www.tritonatm.com/>. Please review release notes for more information.

If you have questions regarding this Technical Bulletin, please contact Technical Support at 1-228-575-3100 or toll free in the U.S. / Canada 1-800-259-6672. Visit [www.tritonatm.com](http://www.tritonatm.com) for additional information. For all ATM parts, repair, and training needs, visit [www.atmgurus.com](http://www.atmgurus.com).

ECO: 1029762  
1030844  
1031120