

TECHNICAL BULLETIN

SUBJECT:
X3 SOFTWARE FIELD UPDATE

TECHNICAL BULLETIN: 17-18
DATE: NOVEMBER 03, 2017

Confidential - Available to all authorized Triton distributors and third party service providers

**X3 SOFTWARE UPDATE AVAILABLE
FOR US, UK, CANADIAN, AND AUSTRALIAN MARKETS**

Triton announces the release of X3 field update software for the ATM models listed below. This release resolves an issue with printer errors not being cleared from the rear service panel. Hardware requirements, release notes, and load files are available at www.tritonatm.com. Program build will be 4.0.0.42a after update.

Country	Model	Screen Size	Load File
US Canada Australia	FT5000 RT2000	10.4"	t-fs-xcse-4.0.0.42a.tr7
UK	FT5000 RT2000	10.4"	t-fs-xuke-4.0.0.42a.tr7

If you have questions regarding this Technical Bulletin, please contact Technical Support at 1-228-575-3100, option 4 or toll free in the U.S. / Canada 1-866-787-4866, option 4. Visit www.tritonatm.com for additional information. For all ATM parts, repair, and training needs, visit www.atmgurus.com.



ALL PARTS ORDERS GET
FREE SHIPPING!*

NO MINIMUM REQUIRED • LOWER 48 STATES ONLY [Learn more](#)