

866-787-4866 21405 B Street, Long Beach, MS 39560



TECHNICAL BULLETIN

SUBJECT:
US Z180 7.4B EMV UPDATE

TECHNICAL BULLETIN: 18-01 DATE: JANUARY 04, 2018

Confidential - Available to all authorized Triton distributors and third party service providers

SOFTWARE ANNOUNCEMENT –

UPDATE REQUIRED FOR ANY US 81XX, 91XX, 96XX, OR 97XX ATM

Triton announces the release of Z180 7.4B EMV software update for the US. Earlier releases, 7.4 and 7.4a, would occasionally print garbled data when printing records at the terminal. Journal uploads to Triton Connect and the transaction processor host were unaffected. The 7.4b release corrects the printing issue for any 81XX/91XX /96XX/97XX model ATM. See release notes at www.tritonatm.com for more information.

Model	EPROM Version	Other Requirements	
81XX	KP01.03	Visa-approved EPP VP-01.01 or greater TDM-50 dispenser APS CP 205-MRS printer	
91XX	KD01.09	SPED version 01.04 or greater	
96XX	SD04.01	Visa-approved EPP VP-01.01 or greater Non-visa SPED SP-01.02 or greater Requires either A, B, or C below: — A: Minimum 2 MB Memory expansion card and quad-port module. — B: Minimum 2 MB memory expansion card and serial speech module. — C: Multifunctional expansion card (available as an upgrade kit 06200-08200).	
96XX PCI	SD06.00	PCI SPED SP-07.00 or greater Requires either A, B, or C below: — A: Minimum 2 MB Memory expansion card and quad-port module** (I/O module). — B: Minimum 2 MB memory expansion card and serial speech module. — C: Multifunctional expansion card (available as an upgrade kit 06200-08200).	
97XX	ZD01.15	SPED version SP-02.05 or greater	

ECO: 1031885

Model	Full Load Software Version	Update Software Version
81XX/91XX	KC990088.24 (color display)	KCT-9988.24 (color display)
	KD990088.24 (monochrome display)	KAT-9988.24 (monochrome display)
	T 11 1 1	To an 11 and 1 and 1 and 1 and 1 and 1
	To enable advanced security module support, the following plug-in must be installed:	To enable advanced security module support, the following plug-in must be installed:
	AVSM0200.B91	AVSM0200.B91
	11, 02,20 200,251	127,021202001252
	To enable EMV support, the following plug-	To enable EMV support, the following plug-
	ins must be installed:	ins must be installed:
	EMVK0100.B91	EMVK0100.B91
	EMVA1100.B91 (or EMVA1101.B91)	EMVA1100.B91 (or EMVA1101.B91)
96XX	XD890080.14 (color display)	XAT-8980.14 (color display)
9011	XD880080.14 (color display) XD880080.14 (monochrome display)	XAT-8880.14 (color display) XAT-8880.14 (monochrome display)
	ADSOUGO.11 (Monocinome display)	(monochrome display)
	To enable advanced security module support,	To enable advanced security module support,
	the following plug-in must be installed:	the following plug-in must be installed:
	AVSM0200.B96	AVSM0200.B96
	To enable EMV support, the following plug-	To enable EMV support, the following plug-
	ins must be installed:	ins must be installed:
	EMVK0100.B96	EMVK0100.B96
	EMVA1100.B96	EMVA1100.B96
	(or EMVA1101.B96)	(or EMVA1101.B96)
96XX PCI	XD920080.05 (color display)	XAT-9280.05 (color display)
	XD910080.05 (monochrome display)	XAT-9180.05 (monochrome display)
	To enable advanced security module support,	To enable advanced security module support,
	the following plug-in must be installed:	the following plug-in must be installed:
	AVSM0200.B96	AVSM0200.B96
	To enable EMV support, the following plug-	To enable EMV support, the following plug-
	ins must be installed:	ins must be installed:
	EMVK0100.B96 EMVA1100.B96	EMVK0100.B96 EMVA1100.B96
	(or EMVA1101.B96)	(or EMVA1101.B96)
97XX	ZD990080.11	ZAT-9980.11
	To enable advanced security module support,	To enable advanced security module support,
	the following plug-in must be installed:	the following plug-in must be installed:
	AVSM0200.B97	AVSM0200.B97
	To enable EMV support, the following plug-	To enable EMV support, the following plug-
	ins must be installed:	ins must be installed:
	EMVK0100.B97	EMVK0100.B97
	EMVA1100.B97	EMVA1100.B97
	(or EMVA1101.B97)	(or EMVA1101.B97)

If you have questions regarding this Technical Bulletin, please contact Technical Support at 1-228-575-3100, option 4 or toll free in the U.S. / Canada 1-866-787-4866, option 4. Visit www.tritonatm.com for additional information. For all ATM parts, repair, and training needs, visit www.atmgurus.com.

