

**SUBJECT:**

**4.1 SOFTWARE UPDATE FOR ARGO FT**

**TECHNICAL BULLETIN: 18-03**

**DATE: MARCH 14, 2018**

**Confidential - Available to all authorized Triton distributors and third party service providers**

**OPTIONAL UPGRADE – RELEASE OF US, CANADIAN, AND AUSTRALIAN VERSION 4.1  
SOFTWARE UPDATE FOR ARGO FT**

Triton announces the release of an ARGO FT 4.1 software update for the US, Canada, and Australia. This release includes an updated modem test and a new configuration option for EMV language selection, as well as correcting a printer error issue with the rear service panel. With the earlier release, printer errors reset from the RSP did not always clear when the printer was in the service position. This issue has been corrected. Software can be found at [www.tritonatm.com](http://www.tritonatm.com).

The following load files are included with this release:

Model	Load File	Country
ARGO FT	t-fs-bcsf-4.1.0.30.tr7	United States/Canada/Australia

After loading software, the program build will be 4.1.0.30 and the screen file will be BCSF0013. See software release notes for more information.

If you have questions regarding this Technical Bulletin, please contact Technical Support at 1-228-575-3100, option 4 or toll free in the U.S. / Canada 1-866-787-4866, option 4. Visit [www.tritonatm.com](http://www.tritonatm.com) for additional information. For all ATM parts, repair, and training needs, visit [www.atmgurus.com](http://www.atmgurus.com).