


SUBJECT:
TRITON CONNECT 6.2 SERVICE PACK 1

TECHNICAL BULLETIN: 22-03
DATE: FEBRUARY 7, 2022

Confidential - Available to all authorized Triton distributors and third party service providers

OPTIONAL SOFTWARE UPGRADE – RELEASE OF TRITON CONNECT 6.2 SP1

Triton announces the release of Triton Connect 6.2 SP1. Service Pack 1 includes new EMV Journal details, Support for internal Anti-skim readers, PNG AD Graphics, Contact-less readers, filter functionality to dashboard, and bugs from initial release.



This release also includes configurable status history limits, configurable header for printing journals to files, corrected a couple of broadcast and surcharge issues. For a full description of changes and updates, see the release notes at www.triton.com.

****Note****

A new comloc will be required if upgrading from 5.x or earlier

If you have questions regarding this Technical Bulletin, please contact Technical Support at 1-228-575-3100, option 3 or toll free in the U.S. / Canada 1-866-787-4866, option 3. Visit www.tritonatm.com for additional information. For all ATM parts, repair, and training needs, visit www.atmgurus.com.