

# TECHNICAL BULLETIN

**CONFIDENTIAL**

**TECHNICAL BULLETIN: 15-06**

**DATE:** June 3, 2015

**SUBJECT:** Release of US EMV Software Version 7.3 and Sankyo ICM330 EMV Card Reader Kit for Triton 9600/9700 Model ATMs

**AVAILABILITY:** All Authorized Triton US Distributors and Third Party Service Providers

This bulletin addresses:	
<input type="checkbox"/>	Hardware Service Issues
<input checked="" type="checkbox"/>	<b>New Kit/Parts Available</b>
<input checked="" type="checkbox"/>	<b>Software Announcements</b>
<input type="checkbox"/>	Technical Tips

Recommended Implementation is:	
<input type="checkbox"/>	Now for all affected units
<input type="checkbox"/>	All affected units during next service visit
<input checked="" type="checkbox"/>	<b>Optional</b>
<input type="checkbox"/>	No implementation required

## DESCRIPTION:

Triton announces the release of US EMV Software Version 7.3 for the 9600 and 9700 ATMs. This software version supports the Sankyo ICM330 US EMV Upgrade Kit (part #06200-00352). Both this software version and the hardware kit are required for EMV level 2 functionality.

These software load files and their release notes can be found on [www.TritonATM.com](http://www.TritonATM.com). Please refer to the Software Release Notes for Hardware compatibility.



**06200-00352**

**US EMV Card Reader Upgrade Kit**

# TECHNICAL BULLETIN

**CONFIDENTIAL**

**TECHNICAL BULLETIN: 15-06**

**DATE: June 3, 2015**

## DESCRIPTION (Cont.):

Software US revision 7.3 also supports the new External Ethernet Kits (part #06200-00246) for 9600 and 9700.



**06200-00246**

**External Ethernet Replacement Kit**

Please review the Release Notes for more details.

If you have questions regarding this Technical Bulletin, please contact Technical Support at 1-228-575-3100 or toll free in the U.S. / Canada 1-800-259-6672.

Visit [www.Triton.com](http://www.Triton.com) for additional information.

For all ATM Parts, Repair, and Training needs, visit [www.atmgurus.com](http://www.atmgurus.com).