







**TECHNICAL BULLETIN: 15-13** 

**DATE: October 16, 2015** 

**SUBJECT: NMD100 Mounting Bracket Improvements for FT5000** 

**AVAILABILITY:** All Authorized Triton Distributors and Third Party Service Providers

This bulletin addresses:		Recommended Implementation is:	
	Hardware Service Issues	Now for all affected units	
	New Kit/Parts Available	All affected units during next service vis	sit
	Software Announcements	X Optional	
	Technical Tips	No implementation required	

## **DESCRIPTION:**

In our continuing effort to provide customers with the most reliable products possible, Triton has worked diligently to improve the NMD100 mounting bracket. Triton has tested and is releasing to our customers a redesigned mounting bracket that offers more support. This bracket utilizes the lower row of mounting holes on the NMD100 dispenser and two handle mount brackets must be installed.



If you have questions regarding this Technical Bulletin, please contact Technical Support at 1-228-575-3100 or toll free in the U.S. / Canada 1-800-259-6672.

Visit www.Triton.com for additional information.

For all ATM Parts, Repair, and Training needs, visit www.atmgurus.com.









**TECHNICAL BULLETIN: 15-13** 

**DATE: October 16, 2015** 

Triton is offering the following upgrade kit for ATMs with either a 2-High, 3-High, or 4-High NMD100 dispenser. This kit is available for purchase through <a href="www.atmgurus.com">www.atmgurus.com</a> as part number 06200-00296.



06200-00296 NMD100 Mech Mount Bracket Upgrade Kit

If you have questions regarding this Technical Bulletin, please contact Technical Support at 1-228-575-3100 or toll free in the U.S. / Canada 1-800-259-6672.

Visit www.Triton.com for additional information.

For all ATM Parts, Repair, and Training needs, visit www.atmgurus.com.