

**SUBJECT:**

**4.1 SOFTWARE FOR ARGO 7 AND ARGO 12**

**TECHNICAL BULLETIN: 19-01**

**DATE: MARCH 12, 2019**

**Confidential - Available to all authorized Triton distributors and third party service providers**


**SOFTWARE ANNOUNCEMENT – OPTIONAL US, CANADIAN, AND AUSTRALIAN 4.1 SOFTWARE UPDATE FOR ARGO 7 AND ARGO 12 X3**

Triton announces the release of X3 4.1 software update for ARGO 7 and ARGO 12 for the US, Canadian, and Australian markets. This update includes previously released 4.1 features, as well as DCC, system flash updates, cardless transactions, and more detailed information for terminal error messages on the out of service screen. See applicable release notes for a detailed description of changes and features.

Software can be found at [www.tritonatm.com](http://www.tritonatm.com). The following load files are included with this release:

Model	Load File	Country
ARGO 7	t-fs-wtcs-4.1.0.41.tr7	US, Canada, Australia
ARGO 12	t-fs-scsf-4.1.0.41.tr7	US, Canada, Australia

After loading software, the program build for ARGO 7 will be 4.1.0.41 and the screen file will be WTCS0045. For ARGO 12, the program build will be 4.1.0.41 and the screen file will be SCSF0031. Release notes can be accessed via Triton's new software download wizard at [www.tritonatm.com](http://www.tritonatm.com).



**Software Download Resources**

Category: **Software**

Serial #:

Product: **ARGO 7**

Platform:

Country:

**Software Download**

Can't Find the Version You Require?  
Contact Technical Support at:  
1-866-787-4868 US or  
1-228-575-3100 International or  
Ask by E-mail.

Platform	Display	Country	Notes	Files
X3	7	US/Canada/Australia		4.1.0.41 X3 ARGO 7 US CAN AUS
X2	7	US/Canada/Australia		4.0.0.38a X2 CE6 ARGO 7 Anti-Skim
X2	7	US		4.0.0.18 SP2 ARGO 7 CE6
X2	7	US/Canada		4.0.0.17a ARGO 7 CE6
X2	7	US		3.3.2 SP3 ARGO 7 US Common AID Update
X2	7	US/Canada		3.3.2 ARGO 7

4.1 software updates for ARGO 15 and ARGO FT were released in September 2018. See Technical Bulletin 18-13 for details.

If you have questions regarding this Technical Bulletin, please contact Technical Support at 1-228-575-3100, option 4 or toll free in the U.S. / Canada 1-866-787-4866, option 4. Visit [www.tritonatm.com](http://www.tritonatm.com) for additional information. For all ATM parts, repair, and training needs, visit [www.atmgurus.com](http://www.atmgurus.com).