

866-787-4866 21405 B Street, Long Beach, MS 39560



TECHNICAL BULLETIN

SUBJECT:

4.1 SOFTWARE RELEASE FOR ARGO X2 CE6 ATMS

TECHNICAL BULLETIN: 19-03

DATE: AUG 2, 2019

Confidential - Available to all authorized Triton distributors and third party service providers


OPTIONAL UPDATE - RELEASE OF US, CANADIAN, AND AUSTRALIAN VERSION 4.1 SOFTWARE UPDATE FOR ARGO 7 AND 12 X2 CE6 ATMS

Triton announces the release of version 4.1 software for ARGO 7 and ARGO 12 X2 CE6 ATMs. This release includes numerous changes and improvements, such as cardless transactions, dynamic currency conversion (DCC), EMV fallback flag, EMV language selection, printer density options, screen changes, and behavior change for unknown dispense. This software requires the Triton X2 CE6 main board.

The following load files are included in this upgrade. The program build after loading will be 4.1.0.42. The screen file for ARGO 7 will be WTCS0046 and the screen file for ARGO 12 will be SCSF0032. Software can be found at www.tritonatm.com.

Model	Load File
ARGO 7	t-fs-wtcs-4.1.0.42.tr6
ARGO 12	t-fs-scsf-4.1.0.42.tr6

For detailed information on the above options and other improvements, please read the full release notes at www.tritonatm.com.



If you have questions regarding this Technical Bulletin, please contact Technical Support at 1-228-575-3100, option 4 or toll free in the U.S. / Canada 1-866-787-4866, option 4. Visit www.tritonatm.com for additional information. For all ATM parts, repair, and training needs, visit www.atmgurus.com.