

866-787-4866 21405 B Street, Long Beach, MS 39560



TECHNICAL BULLET

SUBJECT:

TRITON UNIT SERIAL NUMBER BREAKDOWN

TECHNICAL BULLETIN: 22-05

DATE: MARCH 04, 2022

Confidential - Available to all authorized Triton distributors and third party service providers

TRITON UNIT SERIAL NUMBER BREAKDOWN - UPDATE

The Triton ATM serial number provides basic information about the ATM, such as product family, operating platform, dispenser type, and date of manufacture. This document provides a breakdown of Triton serial numbers.

The unit serial number can be found on the unit label in the top left directly above the barcode.



subject to the following two conditions: (1) This device may not cause harmful interference, and (2)This device must accept any interference received, including interference that may cause undesired operation.

Caution

This is a class A product: In a domestic environment this product may cause radio interference in which case the user may be required to take adequate measures.

If unit contains wireless modem: The antenna(s) used for this transmitter must be installed to provide a separation distance of at least 20 cm from all persons and must not be co-located or operating in conjunction with any other antenna or transmitter.

US PAT. NO. 6,971,322 © Triton Systems of Delaware, LLC.

***'Varning* 'Avertissement'

- *Disconnect all power cords prior to servicing
- *For continued fault protection, follow the correct voltage and current ratings when replacing fuses.
- *Use of this product in a manner other than those described in the user and installation manuals may result in personal injury.
- *DÚbranchez tous les cordons d'alimentation avant l'entretien.
- *Pour la protection de dÚfaut continu, suivez les Úvaluations actuelles tension correcte lors du remplacement des fusibles.
- *L'utilisation de ce produit d'une manibre autre que celles dÚcrites
- dans les manuels utilisateur et d'installation peut entra ner des blessures personnelle.

REMOVAL OR ALTERATION OF THIS LABEL WILL VOID WARRANTY

Example:

L	R	L	7	4	1	Н	1 9	172	4564
1st Letter New Unit	2nd Letter Retail	3rd Letter Lobby	1st ARGO 15			4th ECDM-100	5th & 6th 2019	7th – 9th June 21	Last 4 # Triton Count

1st letterL = New UnitR = Refurbished UnitC = New with Core Parts	 2nd Letter R = Retail F = Financial V = VersaSafe P = Propane 	3rd Letter L = Lobby T = Through the Wall S = VersaSafe M = Propane
1st Number	2nd Number	3rd Number
1 = 1xxx & ARGO 7"	1 = XScale	0 = No cabinet/SKD
2 = 2xxx & ARGO 7"	3 = X2	1 = Business Hour/Business Hour FT Drive-up
3 = Traverse	4 = X3	2 = Level 1/Level 1 FT Drive-up
4 = NDU/Propane	5 = X3 in a housing	3 = VersaSafe Deep Level 1/FT BH Walk-up
5 = 5xxx	6 = X2b (1600)	4 = VersaSafe shallow/ FT Level 1 Walk-up
6 = ARGO 12	7 = X2T (ARGO 7" X2)	

7 = ARGO 15/ARGO FT 8 = VersaSafe

4th Number	4th Number - VersaSafe Only	5th & 6th Numbers
Dispenser	Bill Acceptor	Year of Manufacture
0 = No Mech	1 = AE2800	
1 = TDM 100	2 = SCNL	
2 = TDM 150	3 = SCNXL	
3 = Mini Mech		

2 = TDM 150
3 = SCNXL
3 = Mini Mech
4 = SDD
5 = NMD 50
6 = NMD 100
7th - 9th Numbers
7 = TDM 200
B = TDM 250
A = TDM 50
B = SCDU
D = HCDU
E = G60
H = ECDM-100
J = MMR050

If you have questions regarding this Technical Bulletin, please contact Technical Support at 1-228-575-3100, option 3 or toll free in the U.S. / Canada 1-877-787-4866, option 4. Visit www.tritonatm.com for additional information. For all ATM parts, repair, and training needs, visit www.atmgurus.com.