



TECHNICAL BULLETIN

SUBJECT:

TRITON UNIT SERIAL NUMBER BREAKDOWN

TECHNICAL BULLETIN: 24-04

DATE: SEPTEMBER 16, 2024

Confidential - Available to all authorized Triton distributors and third party service providers

TRITON UNIT SERIAL NUMBER BREAKDOWN - UPDATE

The Triton ATM serial number provides basic information about the ATM, such as product family, operating platform, dispenser type, and date of manufacture. This document provides a breakdown of Triton serial numbers.

The unit serial number can be found inside units top left on the unit label directly above the barcode.



cause harmful interference, and (2)This device must accept any interference received, including interference that may cause undesired operation.

Caution

This is a class A product: In a domestic environment this product may cause radio interference in which case the user may be required to take adequate measures.

If unit contains wireless modem: The antenna(s) used for this transmitter must be installed to provide a separation distance of at least 20 cm from all persons and must not be co-located or operating in conjunction with any other antenna or transmitter.

US PAT. NO. 6,971,322 © Triton Systems of Delaware, LLC.

***\Varning' 'Avertissement'

- *Disconnect all power cords prior to servicing
- *For continued fault protection, follow the correct voltage and current ratings when replacing fuses
- *Use of this product in a manner other than those described in the user and installation manuals may result in personal injury.
- *DÚbranchez tous les cordons d'alimentation avant l'entretien.
- *Pour la protection de dÚfaut continu, suivez les Úvaluations
- actuelles tension correcte lors du remplacement des fusibles.
- *L'utilisation de ce produit d'une manibre autre que celles dÚcrites dans les manuels utilisateur et d'installation peut entra ner des blessures personnelle.

REMOVAL OR ALTERATION OF THIS LABEL WILL VOID WARRANTY

Example:

4 = SDD5 = NMD 50

6 = NMD 100

7 = TDM 200 8 = TDM 250 A = TDM 50 B = SCDU D = HCDU E = G60

F = CDM8240N H = ECDM-100 J = MMR050

L

R

L

7

7th - 9th Numbers

Julian Day of the Year

4

1

H

1 9

Last 4 Numbers

Triton Counter

172

4564

1st Letter 2nd Letter New Unit Retail	3rd Letter Lobby	1st ARGO 15	2nd X3	3rd BH	4th ECDM-100	5th & 6th 2019	7th – 9th Iune 21	Last 4 # Triton Count	
Tion cim Tion	2000)	111100 10	110	211	202111100	2017)c 21	1,1011 001111	
<u>1st letter</u> <u>2nd Letter</u>				3rd Letter					
L = New Unit $R = Retail$				L = Lobby					
R = Refurbished Unit $F = Financial$				T = Through the Wall					
C = New with Core Parts $V = VersaS$			S = VersaSafe						
P = Propane					M = Propane				
		_							
1st Number 2nd Number				3rd Number					
1 = RL16 or ARGO 7 $1 = XScale$				0 = No cabinet/SKD					
2 = RL2 or RT2 or ARGO 7 $3 = X2$				1 = Business Hour/Business Hour FT Drive-up					
3 = Traverse	B = Traverse $4 = X3$				2 = Level 1/Level 1 FT Drive-up				
4 = NDU/Propane	4 = NDU/Propane $5 = X3 in a housing$				3 = VersaSafe Deep Level 1/FT BH Walk-up				
5 = RL5/FT5	RL5/FT5 6 = X2b (RL16 X2)				4 = VersaSafe shallow/ FT Level 1 Walk-up				
6 = ARGO 12	6 = X4	6 = X4							
7 = ARGO 15/ARGO FT	$7 = X2^r$	T (ARGO	7" X2)						
8 = VersaSafe	8 = X4	8 = X4 in a Housing							
			_		_	_			
4th Number		<u>ımber - V</u>	<u>ersaSafe</u>	e Only	•				
Dispenser	Bill Ac	Bill Acceptor				Year of Manufacture			
0 = No Mech	1 = AE	1 = AE2800							
1 = TDM 100	2 = SC	2 = SCNL							
2 = TDM 150	3 = SC	3 = SCNXL							
3 = Mini Mech									

If you have questions regarding this Technical Bulletin, please contact Technical Support at 1-228-575-3100, option 3 or toll free in the U.S. / Canada 1-877-728-6672, option 3. Visit www.triton.com for additional information. For all ATM parts, repair, and training needs, visit www.atmgurus.com.